

Restoring the exterior envelope of this historic building included 100% replacement of slate roofing and underlayment, new copper gutters and downspouts, brick repointing and reconstruction of an original wood parapet railing to conceal AC equipment.

We also renovated the interior main lobby and stair, installing new wood flooring, carpeting and a reception desk.



